PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141079, Building Permit - Commercial Address: 3361 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Mark Harding Partial Thursday, June 25, 2015

Inspection

Corrective Action Required

1 SECOND FLOOR 2ND FLOOR UNITS;

Corrective Action Required

2 THIRD FLOOR UNITS

Corrective Action Required

3 FOURTH FLOOR 1ST LAYER 4TH FLOOR CEILING;

2ND LAYER 4TH FLOOR NEED TO CUT OUT AND CAULK BLOTH LAYERS OF

PENETRATIONS

4-4TH LAYER STAIR CEILING OK

3RD& TRACK STAIRS

Corrective Action Required

4 FIRST FLOOR 2ND FLOOR UNITS; 2ND LAYER - 2HR CONDITIONS - 2ND FLOOR; 2ND LAYER

CEILING - 4TH FLOOR; 1ST LAYER 2HR CONDITIONS - 3RD & 4TH FLOORS;

1ST FLOOR CORRIDOR- HVAC NEED 2 LAYERS UNDER TRUNK LINE AT

ELEVATOR(OK TO ROCK REMAINDER OF HALL.

Corrective Action Required

5 Misc 1

3RD FLOOR UNITS

3207 BACK SIDE OF ELEVATOR NEED 2ND LAYER, KITCHEN SIDE NEEDS 1ST LAYER INSPECTED

THE COLOR SIDE WEEDS 151 LATER WAS LEVEL

-4TH LAYER STAIR CEILING OK

CORRIDOR WALLS- NEED TO INSPECT DAMAGED ROCK FROM MOVING

SPRINKLER LINES ALL CORIDORS-1ST LAYER 2HR WALLS OK UNIT SIDES.

2hr walls 2nd layer

Comments: