

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20143335, Building Permit - Commercial
Address: 200 NE MISSOURI RD, Unit:100, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Thursday, August 13, 2015
Partial Correction 1 Misc 1		OK TO COVER WHEN READY COMPONENTS OF 2-HR FIRE-RATED WALLS AT LOCATIONS: TWO LAYERS 5/8" TYPE X GWB TOP-OUT AT CORR A112 OUTSIDE A114 SOUTH;	
Partial Correction 2 Misc 1		GW B AT 1 HR FIRE-RATED WALLS: OK TO TAPE, MUD, & FIRE-SEAL WHEN READY 5/8" TYPE X GWB INSTALLATION @ FOLLOWING LOCATIONS: A111 E & S; EXISTING LOBBY EAST WALL OPPOSITE A143; ELECT A117 W, S, E WALLS; WALL SEPARATING A139 & A140; RECESSES/INFILLS AT EX CORR 11 @ NEW D.F. & THREE LOCATIONS @ EX CORR 7 N END; A148 OPPOSITE D.F. @ CORRIDOR; A108 N WALL; A135 S, E, N(EXCEPT WF STEEL BEAM @ TOP); A124 N WALL; S WALL OF SPACES 120 BAYS 5 & 6, 123, 122; BEAM WRAP @ 108 N; 113 E & W; 116; 120 N WALL @ BAYS 1-4; 136; 143; 155; FIRE WALLS W/ STAFF LOUNGE A143 @ N & W; HALLWAY SIDE OF SOILED UTILITY A135; A130 & A124 TO 9' AFF; A154 N & W; A116 W, N, E WALLS CORR FACE; 129 N; 130 N; A117 N WALL; A126 NW TO 10' AFF; A118 S; A150 N, W TO 10' AFF; A152 W, S; A150 N & W ABOVE 10' AFF; CORRIDOR FACE OUTSIDE A150 & 152;	
In-wall Inspection	John Borns	Partial	Thursday, August 13, 2015
Partial Correction 1 Misc 1		OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL & SOFFIT FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: A100 E, N, W; 102; 103; 105; 106; 107; 108; 110; 111; 112; 113; 114; 116; 117; 119; 120; PAIN PRE-OP A120 BAYS 1-4; 121; 123; A125 BAYS 2-5; 124; 125; 125 BAYS 6,7,8; 127; 128; 129; 130; 131; 132; 133; A133 BAYS 7,8; EXSTG CORR RECESS @ DOOR 133A; 134; 135; 136; 137; 138; 139-142; 143 WEST; 143; 145; 146; 147; 148; 149; 154; 155; 156; 117 N; [118 S; 150; 151; 152; 126 NW; A150 SE @ DOOR; A101 NORTH WALL; A109;	

**Above Ceiling
Inspection**

John Borns

Partial

Thursday, August 13, 2015

Partial Correction

1 Misc 1

OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: SOFFITS @ A100, 104, 126, 137, 120 @ SINK, 148; SOFFITS @ A127 & A145; **SOFFITS @ A125 N & S;**

Comments: