PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Friday, September 11, 2015

Inspection

Partial Correction

1 Misc 1 1ST FLOOR:

OK TO TAPE, MUD & FIRE-STOP:

RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT STAIRWELL

WALLS. NO COMMON OR UTILITY AREAS

PRE-ROCK:

UNIT 113: GWB WALL AT DEAD SPACE ADJACENT TO CORRIDOR; UNIT 112: LID OF CLOSET AT EXT WALL; UNIT 132: CEILING ABOVE HVAC DUCT AT BR; UNITS 101 & 102: CORR WALL @ COAT CLO;

Partial Correction

2 Misc 1 2ND FLOOR: OK TO TAPE, MUD & FIRE-STOP:

- CORRIDOR CEILING AND WALLS ONE LAYER 5/8" TYPE X GWB - RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT WALLS AT

STAIRWELLS

Partial Correction

3 Misc 1 3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE

X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS.
WALLS AND CEILINGS AT UNITS **302***; 311; **312***; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS EXCEPT

AT ROOF DRAINS;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS

STAIRWELL WALLS NOT READY FOR INSPECTION

Corrective Action Required

4 Misc 1 FIRE-STOPPING AT ROOF DRAIN LOCATIONS SUBJECT TO

INSPECTION WHEN READY

Comments: