

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Tuesday, September 22, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO TAPE, MUD & FIRE-STOP: RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT STAIRWELL WALLS; ELEVATOR MACHINE ROOM; NO OTHER COMMON OR UTILITY AREAS PRE-ROCK: UNIT 113: GWB WALL AT DEAD SPACE ADJACENT TO CORRIDOR; UNIT 112: LID OF CLOSET AT EXT WALL; UNIT 132: CEILING ABOVE HVAC DUCT AT BR; UNITS 101 & 102: CORR WALL @ COAT CLO;	
Partial Correction 2 Misc 1		2ND FLOOR: OK TO TAPE, MUD & FIRE-STOP: - CORRIDOR CEILING AND WALLS ONE LAYER 5/8" TYPE X GWB - RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT WALLS AT STAIRWELLS	
Partial Correction 3 Misc 1		3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS. WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS EXCEPT AT ROOF DRAINS; NO ISSUES FOUND (SUBJECT TO RE-DESIGN PENDING) ON OSB WALL SHEATHING AT: 315 EAST WALL 317 WEST WALL	

*EXCEPT ROOF DRAINS & STAIRWELL WALLS

Partial Correction
4 Misc 1

STAIRWELL WALLS NOT READY FOR INSPECTION

4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE
X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; **CORRIDOR
WALLS ONLY EXCEPT PENETRATIONS TO BE UL CONFORMING;
E428; E429;**

**NO ISSUES FOUND (SUBJECT TO RE-DESIGN PENDING) ON OSB
WALL SHEATHING AT:**

415 EAST WALL

417 WEST WALL

*CONDITION: CHASE TO BE CONSTRUCTED AT FIRE SPRINKLER
LINES

Comments: