

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	John Borns	Partial	Wednesday, September 23, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO COVER WHEN READY: EXTERIOR WALLS; UNIT WALLS; CORRIDOR CEILING AND WALLS; CEILING AT SPACE 111; ABOVE-CEILING AND OSB WALL SHEATHING OK TO COVER WHEN READY AT 119 & 120 EXCEPT DO NOT COVER PENETRATIONS UNTIL APPROVED PER UL DESIGN TO BE SPECIFIED BY A/E;	
Partial Correction 2 Misc 1		2ND FLOOR: OK TO COVER WHEN READY: CORRIDOR CEILING; ALL CEILINGS & WALLS EXCEPT AT ELEVATOR LOBBY	
Partial Correction 3 Misc 1		3RD FLOOR: OK TO COVER WHEN READY: CORRIDOR CEILING; ALL CEILINGS & WALLS EXCEPT AT STAIRWELLS & ELEVATOR LOBBY	
Partial Correction 4 Misc 1		4TH FLOOR: COMPLETION OF WALL CAVITY FIRE-BLOCKING IN PROGRESS. SHIELD/BOCA PLATING OF PLUMBING LINES IN PROGRESS. OK TO COVER WHEN READY ALL CEILINGS & WALLS EXCEPT AT STAIRWELLS & ELEVATOR LOBBY	
Rated Assembly Inspection	John Borns	Partial	Wednesday, September 23, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO TAPE, MUD & FIRE-STOP:	

RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT STAIRWELL WALLS; ELEVATOR MACHINE ROOM; E108; **CORRIDOR CEILING AND WALLS EXCEPT PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E;**

PRE-ROCK:

UNIT 113: GWB WALL AT DEAD SPACE ADJACENT TO CORRIDOR;
UNIT 112: LID OF CLOSET AT EXT WALL; UNIT 132: CEILING ABOVE HVAC DUCT AT BR; UNITS 101 & 102: CORR WALL @ COAT CLO;

Partial Correction
2 Misc 1

2ND FLOOR: OK TO TAPE, MUD & FIRE-STOP:

- CORRIDOR CEILING AND WALLS ONE LAYER 5/8" TYPE X GWB
- RATED CEILINGS AND WALLS AT ALL UNITS EXCEPT WALLS AT STAIRWELLS

Partial Correction
3 Misc 1

3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS.
WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS EXCEPT AT ROOF DRAINS;

NO ISSUES FOUND (SUBJECT TO RE-DESIGN PENDING) ON OSB WALL SHEATHING AT:
315 EAST WALL
317 WEST WALL

*EXCEPT ROOF DRAINS & STAIRWELL WALLS
STAIRWELL WALLS NOT READY FOR INSPECTION

Partial Correction
4 Misc 1

4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR WALLS ONLY EXCEPT PENETRATIONS TO BE UL CONFORMING; E428; E429;

NO ISSUES FOUND (SUBJECT TO RE-DESIGN PENDING) ON OSB WALL SHEATHING AT:
415 EAST WALL
417 WEST WALL
*CONDITION: CHASE TO BE CONSTRUCTED AT FIRE SPRINKLER LINES

Comments: