PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRRES20143037, Building Permit - Residential Address: 513 NE PROMISED VIEW DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyer	Failed	Friday, October 02, 2015
Corrective Action Requir	ed		
1 Misc 1		AMING: ISTALL COLLAR TIES FOR	THE MAIN RIDGE
	RC FF DC LI' FE CE -II W -I	DOF; FB VERTICAL WALL CONT DINING; FB LENAL COM ROOF; FB SPACE AT DUBLE STUD WALL AT B VING RM FIREPLACE SPA BASEMENT EXERCISE R EILING/FURDOWN SPAC NSTALL HANGER FOR TH OOD-BURNING FIREPLA MAKE SURE THE MAXIMU	E LVL CONNECTION ABOVE THE LENAI
	-N FT -L -A R/ -A SF	OF THE SINK BASINS OWER THE FRONT OFFIC LL BASEMENT UNDERSL ATED FOR WET LOCATIO LL THE FEEDERS THAT A HALL BE DE-RATED FOR T	RE INSTALLED IN THE ATTIC SPACE
		UMBING: SULATE THE WATER LI	NES ABOVE MASTER BATH SHOWER

-PROTECT ALL PLUMBING AT THE BOTTOM WALL SOLE PLATE WITH STEEL PLATES THAT PROVIDE EXTRA 2" OF PROTECTION BEYOND THE SOLE PLATE-THROUGHOUT HOUSE.
-COMPLETE ALL PLUMBING TO BATH FIXTURES
-PROTECTION OF THE CSST GAS LINE IS REQUIRED WHEN INSTALLED WITHIN 3" OF THE CEILING SURFACE ABOVE BASEMENT
-PROVIDE ACCESS TO SEWER STACK CLEANOUT INSIDE THE BASEMENT LIVING RM FIREPLACE
-COMPLETE & INSTALL THE PLUMBING INSIDE WALL SPACE (CRAFT RM)

**OK TO INSULATE **BASEMENT NOT COMPLETED. SOME DEFICIENCIES IN THE BASEMENT ARE ALSO INCLUDED

	l Service on - Residential	Khanh Nguyen	Failed	Friday, October 02, 2015
Correctiv	e Action Require	ed		
1	Misc 1	COND GROU COPP GEC A	DUCTOR (GEC) CO INDED CONDUC ER MAIN JUMPE ND EQUIPMEN	S THAT THE GROUNDING ELECTRODE ONNECTS TO THE BUS THAT THE SERVICE TOR IS CONNECTED TO; OR INSTALL A #4 R FROM THE GROUNDING BAR, WHERE THE GROUNDING CONDUCTORS ARE HE SERVICE GROUNDED CONDUCTOR BUS

Comments: