

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Not Ready	Tuesday, October 06, 2015

Partial Correction
1 Misc 1

1ST FLOOR:
OK TO TAPE, MUD & FIRE-STOP:
RATED CEILINGS AND WALLS AT ALL UNITS ELEVATOR MACHINE ROOM; E108; CORRIDOR CEILING AND WALLS; 119 EXCEPT SOUTH WALL; 120 EXCEPT NORTH WALL;

Partial Correction
2 Misc 1

2ND FLOOR: OK TO TAPE, MUD & FIRESTOP: CORRIDOR CEILING AND WALLS; RATED CEILINGS AND WALLS AT: ALL UNITS; 208; 219; 220;

Partial Correction
3 Misc 1

3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS. WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS; 319; 320;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS
STAIRWELL WALLS NOT READY FOR INSPECTION

Partial Correction
4 Misc 1

4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR WALLS ONLY ; E428; E429; [411; 419; 420;

Corrective Action Required
5 Misc 1

PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E;

Comments: