

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141075, Building Permit - Commercial
Address: 3321 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Mark Harding	Failed	Friday, October 09, 2015

Corrective Action Required

1	Misc 1	-install protection plates and plates straps on plates bored at 50% 3rd failed, b,1,2,3 ok for prerock tub walls 4th no bsmt failed for prerock-1,2,3,4 ok,BSMT FAILED bsmt failed again pre-rock failed 9/25,9/30,10/5,10/6,10/7,10/8,10/9. fees due after 2nd inspection.
---	--------	---

Comments: