

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial
Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Thursday, October 15, 2015
Partial Correction 1 Misc 1		TWO TEMPORARY CONDUITS BORED FROM XFMR LOCATION TO NEW BUILDING.	
Partial Correction 2 Misc 1		PERMANENT PVC CONDUITS OK TO COVER FROM XFMR LOCATION TO 30' SOUTH TOWARD NEW BUILDING;	
Partial Correction 3 Misc 1		OK TO COVER WHEN READY SEVEN 4" PVC SECONDARY ELECTRICAL SERVICE CONDUITS FROM BUILDING ENTRY TO SHORT OF SWEEPS AT TRANSFORMER PAD LOCATION	
Rated Assembly Inspection	John Borns	Partial	Thursday, October 15, 2015
Partial Correction 1 Misc 1		1ST FLOOR: OK TO TAPE, MUD & FIRE-STOP: RATED CEILINGS AND WALLS AT ALL UNITS ELEVATOR MACHINE ROOM; E108; CORRIDOR CEILING AND WALLS; 119 EXCEPT SOUTH WALL; 120 EXCEPT NORTH WALL;	
Partial Correction 2 Misc 1		2ND FLOOR: OK TO TAPE, MUD & FIRESTOP: CORRIDOR CEILING AND WALLS; RATED CEILINGS AND WALLS AT: ALL UNITS; 208; 219; 220;	
Partial Correction 3 Misc 1		3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS. WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315;	

317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS; 319; 320;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS
STAIRWELL WALLS NOT READY FOR INSPECTION

Partial Correction
4 Misc 1

4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR WALLS ONLY ; E428; E429; 411; 419; 420; CORRIDOR CEILING

Partial Correction
5 Misc 1

OK TO TAPE, MUD AND FIRE-SEAL CEILINGS AND WALLS AT ELEVATOR LOBBIES AT: 4TH FLR; 3RD FLR; 2ND FLR;

Corrective Action Required
6 Misc 1
Partial Correction
7 Misc 1

PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E;

RATED WALLS AT STAIRWELL SHAFTS: 1" SHAFT LINER IN PLACE FROM 1ST FLR TO 3RD FLR ELEVATION MUST BE FIRE-STOPPED AT ALL PENETRATIONS, HOLES AND JOINT GAPS -- CALL FOR RE-INSPECTION WHEN READY

All Rough Inspection - Commercial

John Borns

Partial

Thursday, October 15, 2015

Partial Correction
1 Misc 1

1ST FLOOR:
OK TO COVER WHEN READY: EXTERIOR WALLS; UNIT WALLS; CORRIDOR CEILING AND WALLS; CEILING AT SPACE 111; ABOVE-CEILING AND OSB WALL SHEATHING OK TO COVER WHEN READY AT 119 & 120 EXCEPT DO NOT COVER PENETRATIONS UNTIL APPROVED PER UL DESIGN TO BE SPECIFIED BY A/E;

Partial Correction
2 Misc 1

2ND FLOOR:
OK TO COVER WHEN READY: CORRIDOR CEILING; ALL CEILINGS & WALLS EXCEPT AT ELEVATOR LOBBY

Partial Correction
3 Misc 1

3RD FLOOR:
OK TO COVER WHEN READY: CORRIDOR CEILING; ALL CEILINGS & WALLS EXCEPT AT STAIRWELLS & ELEVATOR LOBBY

Partial Correction
4 Misc 1

4TH FLOOR:
COMPLETION OF WALL CAVITY FIRE-BLOCKING IN PROGRESS. SHIELD/BOCA PLATING OF PLUMBING LINES IN PROGRESS. OK TO COVER WHEN READY ALL CEILINGS & WALLS EXCEPT AT STAIRWELLS & ELEVATOR LOBBY

Partial Correction
5 Misc 1

OK TO COVER WHEN READY OSB SHEAR WALL SHEATHING AT: EAST STAIRWELL FULL HEIGHT; WEST STAIRWELL FULL HEIGHT;

Partial Correction
6 Misc 1

EAST & WEST WALLS AT SPACES 128 & 129;

OK TO COVER WHEN READY ELEVATOR LOBBY CEILINGS AND
WALLS AT 4TH FLOOR; 3RD FLOOR; 2ND FLOOR; **1ST FLOOR**
INCLUDING OSB AT WEST WALL

Comments: