PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150014, Building Permit - Commercial Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Not Ready Wednesday, October 28, 2015

Inspection

Corrective Action Required

1 Misc 1 MAIN CORRIDOR AT LEVELS 2 & 3: FIRE-STOP ALL OPENINGS AND

PENETRATIONS AT WALLS AND CEILINGS; THEN REQUEST

INSPECTION.

Rated Assembly John Borns Passed Wednesday, October 28, 2015

Inspection

Partial Correction

1 Misc 1 1ST FLOOR:

OK TO TAPE, MUD & FIRE-STOP:

RATED CEILINGS AND WALLS AT ALL UNITS ELEVATOR MACHINE ROOM; E108; CORRIDOR CEILING AND WALLS; 119 EXCEPT

SOUTH WALL; 120 EXCEPT NORTH WALL;

Partial Correction

2 Misc 1 2ND FLOOR: OK TO TAPE, MUD & FIRESTOP: CORRIDOR CEILING

AND WALLS; RATED CEILINGS AND WALLS AT: ALL UNITS; 208;

219; 220;

Partial Correction

3 Misc 1 3RD FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE

X GWB AT: CORRIDOR CEILING; ELECT & DATA RMS WALLS. WALLS AND CEILINGS AT UNITS 302*; 311; 312*; 313; 314; 315; 317; 318; 321; 323; 324; 327; 332; 333; CORRIDOR WALLS; 319;

320;

*EXCEPT ROOF DRAINS & STAIRWELL WALLS STAIRWELL WALLS NOT READY FOR INSPECTION

Partial Correction

4 Misc 1 4TH FLOOR: OK TO TAPE, MUD & FIRE-STOP ONE LAYER 5/8" TYPE

X GWB AT: UNITS 412; 413*; 414*; 423; 424; 427*; CORRIDOR WALLS ONLY; E428; E429; 411; 419; 420; CORRIDOR CEILING

Partial Correction 5 Misc 1

OK TO TAPE, MUD AND FIRE-SEAL CEILINGS AND WALLS AT ELEVATOR LOBBIES AT: 4TH FLR; 3RD FLR; 2ND FLR;

Corrective Action Required 6 Misc 1

PROTECTION OF PENETRATIONS TO BE SPECIFIED BY A/E;

Comments: