

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20152661

Address: 319 SE DOUGLAS ST, Unit:313, LEES SUMMIT, MO 64063

Inspected On: Thursday, December 10, 2015

Inspected By: John Borns

Expiration Date: 12/17/2015 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Thursday,

Codes Commercial December 10, 2015

Corrective Action Required:

1 Misc 1 RESOLVE FIRE DEPARTMENT ISSUES.

Corrective Action Required:

2 Misc 1 WHEN MIRROR IS INSTALLED SET BOTTOM OF GLASS NO MORE

THAN 40" ABOVE FLOOR.

Corrective Action Required:

3 Misc 1 NEC 408.4 CONSTRUCT ACCURATE ELECTRICAL PANEL SCHEDULE.

NUMBER POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR CONTINUATION SYMBOLS EXCEPT @ MULTIPLE POLE

BREAKERS, LABEL UNUSED BREAKERS "SPARE".

APPLY SEALANT AT GAP AT BOTTOM OF RESTROOM WATER CLOSET.