

Inspection Summary

Permit #: PRCOM20152121, Building Permit - Commercial
Address: 1601 SW MANOR LAKE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Final Building Inspection - Commercial	Mark Harding	Failed	Thursday, December 17, 2015

Corrective Action Required

1	Misc 1	install uffer ground and isolate nuetrals and grounds at panel.
		install fire extinguisher per FDwhen complete

All Rough Inspection - Commercial	Mark Harding	Failed	Thursday, December 17, 2015
--	--------------	--------	-----------------------------

Corrective Action Required

1	Misc 1	FRAMING INSPECTION ELECTRICAL ROUGH INSPECTION OK TO ROCK -EXCEPT AT UFFER GROUND AND AT PANEL FOR INSPECTION OF SE CABLE. isolate nuetrals and ground and install uffer ground from grounding bus bar to uffer
---	--------	--

Comments: