

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20150014

Address: 508 NW MURRAY RD, LEES SUMMIT, MO 64081

Inspected On: Friday, January 22, 2016

Inspected By: John Borns

Expiration Date: 2/11/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Friday, January 22,

Codes Commercial 2016

Corrective Action Required:

1 Misc 1 COMPLETE PERMANENT BALCONY GUARDS WHERE MISSING

SECTIONS OR PARTS. EXAMPLE: 203D. WORK IN PROGRESS.

Corrective Action Required:

2 Misc 1 SEAL ALL PENETRATIONS/HOLES IN EXTERIOR BUILDING WALLS,

INCLUDING AT LUMINAIRES AND AROUND INTAKE LOUVERS AT

UNIT MECHANICAL CLOSETS.

Corrective Action Required:

3 Misc 1 TEMPORARY PASSAGE PROVISIONS TO BE ESTABLISHED AT 1ST FLR

CORRIDOR WEST -- NOT REQUIRED FOR EMERGENCY EGRESS, BUT

SUBJECT TO REASONABLE SAFETY STANDARDS WHEN

CONSTRUCTED.

Corrective Action Required:

6 Misc 1 TRIM PLUMBING CLEANOUT RISERS TO NEAR GRADE.

Corrective Action Required:

7 Misc 1 DEPARTMENTS APART FROM CODES:

FIRE DEPARTMENT: OK PER CPT WEISSENBACH

PUBLIC WORKS: SIDEWALK APPROVAL PENDING; OK FOR TCO

PLANNING: SEE SEPARATE REPORT WATER DEPARTMENT: APPROVED

Corrective Action Required:

8 Misc 1 LADDER TO ROOFTOP SHOULD FACE ACCESS SIDE OF ROOF HATCH.

CORRECTION INITIATED.

Corrective Action Required:

9 Misc 1 COMPLETE ROOFING/SHEET METAL WORK. REMOVE ALL

EQUIPMENT, TOOLS, MATERIALS. LEAVE NO DEBRIS ON ROOF

MEMBRANE.