

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRRES20152158, Building Permit - Residential
Address: 2400 SW HICKORY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Monday, February 22, 2016

Corrective Action Required

1 Misc 1

- fire stopping through out, garage chase, flu Chase 1st floor, dinning room dead space,
- support truss per plans over mstr and joist hanger where required, missing joist hanger , see truss layout and support truss to header in wall, add header in bearing wall, support truss to dbl truss.
-
- Fire stop front bedroom wall at ceiling line.
- install header to support trust over master closet door.
- Install three studs between the windows rear wall of first floor. incomplete, mstr rear wall missing window ,,,,nothing addressed
- Support truss over mstr bath and bedroom Install contact Truss engineer or intall hangers, bearing wall, at locations designed.
- provide engineers report on dbl 2x10 installed to support truss mstr closet side.
- fees due after the 2nd inspection.

Comments: