PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20152186, Building Permit - Residential Address: 3908 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Monday, May 02, 2016
Corrective Action Require 1 Misc 1	-FIREB CODE. **THE EXCESS INSUL/ OR YOU -FILL IN FROM PLATE **SECU Sec. 7 A. Door ja void ex openin the str	USE 3/4" SHEATHING VERTICAL SHEATHING IS S SIVE GAPS. YOU CAN SECUE ATION TO THIS WALL TO M U CAN LAYER ANOTHER SH N WITH SOLID WOOD TO VO 12" ABOVE THE STRIKE PLA URITY CODE: -1407.3 Door jambs. ambs shall be installed with kists between the strike sid	EET THE CODE REQUIREMENT, EATHING. DID ALONG STRIKE PLATE SIDE, TE TO 12" BELOW THE STRIKE n solid backing in a manner so no e of the jamb and the frame twelve (12) inches each side of

Comments: