

Inspection Summary

Permit #: PRRES20160412, Building Permit - Residential
Address: 309 SE MILL CREEK DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mike Copeland	Not Ready	Tuesday, May 10, 2016

Corrective Action Required
1 Misc 1 2ND REQUEST, NO EROSION CONTROL

Erosion Control	Mike Copeland	Not Ready	Tuesday, May 10, 2016
------------------------	---------------	-----------	-----------------------

Corrective Action Required
1 Misc 1 NO EROSION CONTROL IN PLACE. MUD IN THE STREET

Erosion Control	Mike Copeland	Failed	Tuesday, May 10, 2016
------------------------	---------------	--------	-----------------------

Corrective Action Required
1 Misc 1 NO EROSION CONTROL IN PLACE. MUD IN THE STREET

Comments: