

## Inspection Summary

Permit #: PRCOM20150016, Building Permit - Commercial  
Address: 518 NW MURRAY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	John Borns	Partial	Wednesday, May 11, 2016
Partial Correction 1      Misc 1	OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: [C105]; [C106]; [102]; [125]; [NORTH STORAGE ROOM @ 2ND FLOOR]; RAMP[105]; CORRIDOR[110] AFTER INSULATION IS COMPLETED AT NORTH; SOFFITS @ [C107]; CANOPY AT MAIN ENTRANCE;		
Partial Correction 2      Misc 1	OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: PEDESTRIAN BRIDGE [C205] CORRIDOR ONLY; C-102; C-103; C-104; C-127; R-103;		
Partial Correction 3      Misc 1	OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: [C105]; [C106]; [102]; [125]; [NORTH STORAGE ROOM @ 2ND FLOOR]; RAMP[105]; CORRIDOR[110] AFTER INSULATION IS COMPLETED AT NORTH; SOFFITS @ [C107];		
Partial Correction 4      Misc 1	OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: PEDESTRIAN BRIDGE [C205] CORRIDOR ONLY; C102; C103; C104; C127; R103; [R101; R012; R107; C101; C105; C106; C107; C112; C117; C118; C121; C123; C126;  <b>KITCHEN C111 OK EXCEPT EXCLUDE...</b> <b>- WEST 4' NOT READY (CUT BORDER TILE OK HERE)</b> <b>- RECESS TO ELEVATOR LOBBY NOT READY</b>		

**Comments:**