

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit #: PRPWFC20160041, Public Works Infrastructure Permit - Commercial  
Holiday Inn Express (1201 NW Innovation Pkwy.)FDP  
Address: 1201 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
PW-Water Line - Fire Hydrant	Steve Robbins	Partial	Wednesday, June 01, 2016

Informational

- 1 Inspected thrust block coming out of building, everything is good coming out of the building.

Corrective Action Required

- 2 Both fire hydrants are installed, fire hydrant 1 on south side is installed with thrust block. On the north side 2 is installed with no thrust block because hydrant was crooked , but is now straightened out.

**Comments:**

---