

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20150016

Address: 518 NW MURRAY RD, LEES SUMMIT, MO 64081

Inspected On: Friday, June 17, 2016

Inspected By: John Borns

Expiration Date: 7/7/2016 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Friday, June 17,

Codes Commercial 2016

Corrective Action Required:

6 Misc 1 BACKFLOW PROTECTION REQ'D AT ICEMAKER, COFFEE MAKERS,

CARBONATED BEVERAGE FEED LINE, ETC -- TO BE VERIFIED

Corrective Action Required:

7 Misc 1 FIRESTOP HORIZONTAL CHASE AT ELEVATOR MACHINE ROOM

Corrective Action Required:

8 Misc 1 SEAL ALL EXTERIOR WALL OPENINGS

Corrective Action Required:

1 Misc 1 COMPLETE FINISH SITEWORK

Corrective Action Required:

2 Misc 1 RESOLVE ANY PLANNING ISSUES

RESOLVE ANY FIRE DEPT ISSUES
RESOLVE ANY WATER DEPT ISSUES

RESOLVE ANY PUBLIC WORKS DEPT ISSUES

Corrective Action Required:

3 Misc 1 ROOFTOP:

-HINGE KITS REQ'D ON GREASE EF'S

-FINAL CLEAN ROOF SURFACE OF UNUSED MATERIAL AND DEBRIS

Corrective Action Required:

4 Misc 1 COMPLIANT HANDRAILS REQUIRED AT EXTERIOR STAIR AT SW.

TEMPORARY PROVISONS ARE ACCEPTABLE.

Corrective Action Required:

5 Misc 1 COMPLIANT GUARDS AND HANDRAILS REQUIRED AT INTERIOR

STAIR SW AND RAMP SW. TEMPORARY PROVISONS ARE

ACCEPTABLE.