

## Inspection Summary

Permit #: PRFW20160817, Fireworks Permit

Address: 194 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Building and Planning Inspections (FW)</b>	Mike Copeland	Failed	Friday, June 24, 2016

### Corrective Action Required

1 Misc 1

KCP&L PROVIDED A TEMP METER/ ENCLOSURE.

THE ENCLOSURE IS EQUIPPED WITH TWO 20 AMP GFCI BREAKERS/FUSES. THE LEFT ONE TRIPPED WHEN TESTED AND WILL NOT RE-SET. THE RIGHT FUSE WILL NOT TRIP WHEN TESTED WITH GFCI.

THE ENCLOSURE IS REQUIRED TO BE GROUNDED.

### Comments: