

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit #: PRCOM20160805, Building Permit - Commercial  
HT SOLUTIONS - FOUNDATION AND UNDERSLAB  
Address: 1440 SE BROADWAY DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
Erosion Control	Brice Lawson	Partial	Monday, July 25, 2016

Corrective Action Required

- 1 Your project is in violation of the Erosion and Sediment control policy.  
Brice Lawson 07/25/2016 4:01 PM

Add the construction entrance per the plans and remove any debris that has been tracked onto the roadway.

**Comments:**

---