

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRRES20160937, Building Permit - Residential
Address: 400 SE MILL CREEK DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mike Copeland	Failed	Tuesday, August 09, 2016

Corrective Action Required

1 Misc 1

-MASTER BED VAULT FIREBLOCKING USED REQUIRED TO BE MINIMUM 3/4" PLY OR 1/2" GYP.

-REAR DECK ATTACHED TO CANTILEVER, THIS MUST BE HEADERED OR INSTALL POSTS.

OKAY INSULATE

Gas Service Inspection - Residential	Mike Copeland	Failed	Tuesday, August 09, 2016
---	---------------	--------	--------------------------

Corrective Action Required

1 Misc 1

ONLY ABOUT 1.5 FEET OF GAS PIPE ON PRESSURE AT THE FURNACE DUE TO SHUT OFF, AND LIKELY RUINED THE FURNACE REGULATOR.

****2ND INSPECTION, NO TEST PRESSURE AT ALL.*****

Comments: