PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20160939, Building Permit - Commercial Address: 3320 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Electrical Service Inspection - Commercial	Khanh Nguyen	Failed	Tuesday, October 25, 2016
Corrective Action Required			
1 Misc 1	CONDU- TAPE TAPE -AT PC INSIDE -AT PC -CANN TRAILE MORE SAME -GROU TO A G GROU -REBO FRAME WITH -SECUE -BOND	DLE, PROTECT GROUNDING RACEWAY DLE, DRIVE GROUND ROD FI IOT SPLIT THE FEEDER FROM R. THERE MUST BE ONE DI THAN SIX BREAKERS ALL G LOCATION IND THE DISCONNECTING N ROUNDING ELECTRODE SY NDING ELECTRODE SYSTER ND THE #8 BONDING CONE E. THE CURRENT BONDING A WORKING ONE RE RACEWAY AT TRAILER P	ING CONDUCTORS WITH GREEN ELECTRODE CONDUCTOR LUSH TO GROUND M THE SERVICE AT POLE AT SCONNECTING MEAN WITH NO ROUPED TOGETHER AT THE MEAN (AS INDICATED ABOVE) STEM PER CODE. INSTALL A FOR THE TRAILER DUCTOR TO TRAILER STEEL DEVICE NEEDS TO BE REPLACED ER CODE. REW THAT ALLOWS AT LEAST

Comments: