

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161080, Building Permit - Commercial
Address: 521 SE 2ND ST, Unit:B, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Final Building Inspection - Commercial	John Borns	Failed	Tuesday, November 22, 2016

Corrective Action Required

1 Misc 1

LICENSE TAX DUE AND OWING

Corrective Action Required

2 Misc 1

RESOLVE FIRE DEPARTMENT ISSUES

Corrective Action Required

3 Misc 1

CHECK ALL ELECTRICAL RECEPTACLES TO ENSURE ALL ARE MOUNTED SOLID TO BOX -- NONE "SOFT" OR LOOSE SIDE-TO-SIDE. USE SPACERS WHERE NEEDED.

Corrective Action Required

4 Misc 1

PROVIDE INFORMATION TO OCCUPANT ON LOCATION OF RE-SETS FOR ALL GFI-PROTECTED ELECTRICAL RECEPTACLES.

Corrective Action Required

5 Misc 1

NEC 408.4: LABELING OF ELECTRICAL CIRCUIT POSITIONS AT PANEL(S): EACH BREAKER POSITION MUST BE LABELED. MUST BE LEGIBLE, SPECIFIC. IF PANEL SCHEDULE IS USED NUMBER POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR CONTINUATION SYMBOLS EXCEPT @ MULTIPLE POLE BREAKERS. LABEL UNUSED BREAKERS "SPARE". LABEL UNOCCUPIED POSITIONS "SPACE".

Corrective Action Required

6 Misc 1

POWER NOT INSTALLED FOR TV'S AT PATIENT CHAIRS

Corrective Action Required

7 Misc 1

DOOR FOR MED GAS ROOM NOT SHOP-LABELED 1HR RATED

Corrective Action Required

8 Misc 1

SEAL BASE OF RESTROOM WATER CLOSET TO FLOOR

Comments: