

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit: PRPWFR20161925, Development Services Infrastructure Permit - Residential

Address: Monticello 2nd Plat

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed.

Inspection Item:

Street - Surface Course

Barton Reese

November 28, 2016

On Nov. 23, 2016 Superior Bowen placed the asphalt surface. The surface will need to be touched up in several places. Some of the Joints and Transition(s) are rough. In places the surface is rough. In places there are splotches of a tar-like substance on the surface (splotches may have came off the nine-tire roller). The asphalt surface will have to be repaired/touched up.

Please note: the City reserves the right to do further inspections, and possibly testing, on the asphalt pavement.
