

Inspection Summary

Permit #: PRCOM20161080,
Address: 521 SE 2ND ST, Unit:B, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Final Building Inspection - Commercial	John Borns	Not Ready	Wednesday, December 07, 2016

Corrective Action Required

1	Misc 1	ELECTRICAL WIRING AND BOXES TO POWER TV'S AT PATIENT CHAIRS NOT EXPOSED FOR INSPECTION. LICENSED ELECTRICAL CONTRACTOR TO MAKE ARRANGEMENTS WITH INSPECTOR TO INSPECT ABOVE CEILING.
---	--------	--

Comments: