

Certificate of Occupancy

Permit #: PRCOM20162806
Address: 100 SW 3RD ST, Unit:B, LEES SUMMIT, MO 64063
Inspected On: Thursday, December 29, 2016
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

| | | | |
|---|-------------|----------|--------------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Occupancy Inspection - John Borns Codes Commercial | Full C of O | | Thursday, December 29, 2016 |

Comments: RESTROOM -- CONDITIONS / EXCEPTIONS:

- 60" TURN CIRCLE NOT MET DUE TO EXISTING WALLS
- 24" GRAB BAR INSTALLED AT REAR WALL IN LIEU OF 36" PER ICC -- DUE TO EXISTING WALLS
FIXTURE PIPING LOCATIONS
- IF MIRROR IS INSTALLED ENSURE BOTTOM OF REFLECTIVE SURFACE IS $\leq 40"$ AFF
- PADDING SHOULD BE INSTALLED AT PIPING BELOW SINK