

**PLANNING AND DEVELOPMENT**

**Final Inspection Report**  
**Inspection Summary**

**Permit #:** PRCOM20160414, Building Permit - Commercial

**Permit Project Title:** HT SOLUTIONS

**Address:** 1440 SE BROADWAY DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Planning</b>	Jennifer Thompson, Planner	Temporary C of O	Friday, January 27, 2017

Corrective Action Required

1 Landscaping is incomplete.

Corrective Action Required

2 Grass has not been established.

Corrective Action Required

3 Screening for ground mounted units has not been installed.

Corrective Action Required

4

Corrective Action Required

5 General site clean-up is needed.

**Comments:**