

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20162583, Building Permit - Commercial
Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Alarm Test	Michael Weissenbach	Passed	Thursday, February 09, 2017
Final Building Inspection - Commercial	John Borns	Partial	Thursday, February 09, 2017
Partial Correction 1 Misc 1		SPACES OK FOR USE: 1D22 EKG/VASCULAR; 1C133; 1C216; 1C137; 1C101;	
Above Ceiling Inspection	John Borns	Partial	Thursday, February 09, 2017
Partial Correction 1 Misc 1		OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: 1C216; 1C133; C137; [1D25]; 1C217; 1C218A; 1C219; 1C221; 1C223; 1C218 INCLUDING EAST 1/2; 1D24; 1D26 AFTER RATED WALL STICKERS ARE ADHERED TO WALL RATHER THAN TO M/E/P COMPONENTS; 1C117-1C120 SUBJECT TO RE-INSPECTION AFTER RENOVATION PROCEEDS; 1C101;	
Occupancy Inspection - Fire	Michael Weissenbach	Temporary C of O	Thursday, February 09, 2017

**Final Building
Inspection -
Commercial**

John Borns

Failed

Thursday, February 09, 2017

Partial Correction

1 Misc 1

SPACES OK FOR USE: 1D22 EKG/VASCULAR; 1C133; 1C216; 1C137;
1C101;

Corrective Action Required

2 Misc 1

1C218; 1D25; 1D26; 1C1`22; 1C123:

- ELECTRICAL PANEL NOT IDENTIFIED
- CIRCUITS AT PANEL NOT IDENTIFIED
- DISCONNECT NOT LABELED
- ENSURE ALL ELECTRICAL RECEPTACLES HAVE YOKE SPACERS IF
NEEDED AND ARE MOUNTED SOLID
- COPPER DRAIN PIPES NOT SECURED ABOVE FLOOR SINK
- ONE EMERGENCY RECEPTACLE NOT HOT FOR TEST

Comments: