

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRCOM20151897, Building Permit - Commercial
Address: 1201 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Thursday, February 16, 2017

Partial Correction
1 Misc 1

OK TO COVER WHEN READY BURIED CONDUIT FOR SITE ELECTRICAL AT FOLLOWING LOCATIONS: FROM L.P. #1 TO #2 TO #3; #1 TO #2 TO #3; #11 TO #4 TO #5; (A) TO #10 TO #1; (B) TO #9; **AROUND N ENTRANCE;**

Partial Correction
2 Misc 1

2 BASES SW CORNER OF BUILDING.
2 AT NORTH END
1 A NW OF BUILDING APAPROVED

Rated Assembly Inspection	John Borns	Partial	Thursday, February 16, 2017
----------------------------------	------------	---------	-----------------------------

Partial Correction
1 Misc 1

OK TO COVER WHEN READY COMPONENTS OF RATED WALL ASSEMBLY AT: ONE LAYER 5/8" TYPE C GWB PRE-ROCK FOR ELECTRICAL PANELS AT SPACES 316; 216;

ENSURE MAX 1/8" MARGINS AT ELECT BOX CUT-OUTS.

Partial Correction
2 Misc 1

ELEVATOR SHAFT
4 LAYERS (W/ REILIENT CHANNEL) 5/8" TYPE X GWB AT LID
TWO LAYERS 5/8" TYPE X GWB AT N,E,S WALLS COMPLETE, TAPED, AND MUDDDED

Partial Correction
3 Misc 1

OK TO COVER AT STAIRWELLS: 2 LAYERS 5/8" TYPE X GWB AT

WALLS BOTH STAIRWELLS; RESILIENT FURRING + 5/8" TYPE X
GWB AT LANDING CEILINGS

Partial Correction
4 Misc 1

OK TO TAPE, MUD, AND FIRE-STOP WHEN READY RATED WALLS
AND CEILINGS AT: 4TH FLOOR; 116; 3RD FLOOR INCLUDING
ELECTRICAL ROOM & BACK OF HOUSE; 2ND FLOOR INCLUDING
ELECTRICAL ROOM; CORRIDORS; 2ND FLOOR ELEVATOR LOBBY

Partial Correction
5 Misc 1

**LAUNDRY CHUTE: OK TO COVER WHEN READY: 1ST LAYER 5/8"
TYPE X GWB;**

All Rough Inspection - John Borns
Commercial

Partial

Thursday, February 16, 2017

Partial Correction
2 Misc 1

RESILIENT CHANNEL PER UL U522 OK TO COVER WHEN READY AT
WALLS AND CEILINGS AT: 4TH FLOOR EXCEPT AT STAIRWELLS
AND ROOMS 430 AND 432; 3RD FLOOR; 2ND FLOOR; 101; 103;
105; 107; 109; 111; 112, 116, 118, 127, 129, 131, 133, 152;

Partial Correction
1 Misc 1

OK TO COVER WHEN READY WALLS AND CEILINGS AT: 4TH
FLOOR; 3RD FLOOR; 2ND FLOOR INCLUDING 228; 230; 232; AND
GUEST LAUNDRY @ ELEVATOR B/O HOUSE; ELEVATOR SHAFT;
BOTH STAIRWELLS; TELECOM 114; 111 LAUN W WALL; 119 W
WALL; 128 PANTRY W WALL; 106 & 150 W WALL; 115; 117; **CONF
RM; SWIMMING POOL - PARTIAL AT CENTER; PANTRY; KITCHEN;
LINEN 119/MECH; 118; 116 N WALL;**

Comments: