## PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20162583, Building Permit - Commercial Address: 20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underslab Plumbing Inspection - Commercial	John Borns	Partial	Friday, February 17, 2017
Partial Correction 1 Misc 1	۲ ۲	OK TO COVER WHEN READY UND WASTE, & VENT PIPING AT: 1C12 RELOCATED SCRUB SINK @ 1C21 NOTE IPC 312 / IRC P2503.5.1 RE PRESSURE-TESTING PIPING SYSTE	2; 1D24; 1C217; 1C218; 1C218A; 9; 1C117; 1C121; 1C123; QUIREMENT FOR
In-wall Inspection	John Borns	Partial	Friday, February 17, 2017
Partial Correction 1 Misc 1	+ 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	OK TO COVER WHEN READY LIGH + IN-WALL SYSTEMS AT FOLLOWI WALL; 1C216; 1C217; CUT-IN DO 1D25; 1D26; IN-FILL AT 1D22 N W 1D26 W WALL B/F; 1D221 E WAL CONTINGENT ON SEGMENT OF C SMOKE-SEALED; C137; E/NE WAL WALLS; [1C118] E & NW; [1C120] 2 BOCA PLATES IN PLACE; WALL A [1C118] W WALL; [1C118A] E WA [218] SE CORNER; [1C219] E & W S; N WALL OF NEWLY-ENCLOSED SOUTH; [1C211] N WALL B/F; FRA (1C101) & (1C197) B/F; [1C101]; \$	OR 1C219; 1D23 NW WALL B/F; VALL B/F; 1D24 B/F; 1D25 O/SF; L B/F; 1C223; 1C221 ORRIDOR SMOKE WALL BEING L; 1C120 & 121 B/F; 1C218 E & S S WALL; [1C218] N WALL AFTER AT/ADJACENT TO DOOR (1D23); LL; [1C119] S WALL; CHASE AT WALLS; WING WALL @ [1C219] CLOSET PER PR#5 AT [1D23] MING AT DOOR OPENINGS

B/F = BOTH FACES O/SF = OUTSIDE FACE

Final Building Inspection - Commercial	g John Born	s Partial	Friday, February 17, 2017
Partial Correc	tion		
1 Mis	c 1	SPACES OK FOR USE: 11	D22 EKG/VASCULAR; 1C133; 1C216; 1C137;
		1C101; 1C117-1C120 B	LOOD DRAW AREA; <b>1C124; 1C125;</b>
Corrective Act	ion Required		
2 Mis	1 1C218; 1D25; 1D26; 1C1`22; 1C123:		
		- ELECTRICAL PANEL NO	DT IDENTIFIED
		- CIRCUITS AT PANEL N	OT IDENTIFIED
		- DISCONNECT NOT LA	BELED

Comments: