

FIRE DEPARTMENT

PLANS REVIEW CONDITIONS

Permit No: PRCOM20162048

H&M Applicant:

Location:

Project Title:

820 NW BLUE PKWY, LEES

SUMMIT, MO 64086 1390

Type of Work:

Occupancy Group: M

Description: NEW TENANT FINISH FOR

H&M

Construction Type: Type IIB (Unprotected)

Map Page: 195A

Date: March 01, 2017

rr ·······

ABSOLUTE FIRE INC 13906 CENTURY LN GRANDVIEW, MO 64030

Primary: (816) 737-9991

Listed below are requirements from our department for the project noted above. If you have any additional questions, please contact our department for further clarification.

Sprinkler Plan Review Reviewed By: Joe Dir Released for Construction

1. 2012 IFC 901.6- Inspection, testing and maintenance. Fire detection, alarm and extinguishing systems shall be maintained in an operative condition at all times, and shall be replaced or repaired where defective. Not required fire protection systems and equipment shall be inspected, tested and maintained or removed. EXISTING FIRE SPRINKLER SYSTEM SHALL BE CURRENT WITH ALL SERVICE, MAINTENANCE, TESTING PRIOR TO STARTING TENANT FINSIH WORK. A CURRENT SERVICE TAG SHALL BE POSTED ON THE SYSTEMS RISER.

The applicant understands that the requirements listed above must be corrected to conform to applicable City Codes and Ordinances.