PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20162248, Building Permit - Residential Address: 1353 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - Khanh Nguyen Failed Tuesday, March 28, 2017

Codes Residential

Corrective Action Required

1 Misc 1

-SEAL EXTERIOR WALL PENETRATION AT GAS LINE

-AC UNIT: ID THE UNGROUNDED CONDUCTOR WITH PROPER COLOR; SECURE WHIP WITHIN 12" OF DISCONNECT; UNDERSIZED

WHIP CONDUCTOR. MIN. AMPACITY IS 37 AMP

-INSTALL MAXIMUM 3.5" HANDRAIL FOR DECK STAIR

-GROUT GAP BETWEEN THE DECK FIREPLACE HEARTH SLABS

-SUPPORT DECK FIREPLACE TV YOKE

-PROVIDE POWER TO ALL OUTDOOR RECEPTACLES. ALL

OUTDOOR RECEPTACLES SHALL BE GFCI-PROTECTED. THE FRONT

ENTRY RECEPTACLE NOT TRIPPING. CHECK ALL OF THEM

-SUPPORT BOTH PLIES OF DECK BEAM

-THE GARAGE-PANTRY DOOR NOT SELF-CLOSING

-THE STAIR WINDER TREADS SHALL HAVE MIN. 6" OF DEPTH AT THE NARROWEST END. BOTH ADJACENT WINDER TREADS MUST

HAVE CONSISTENT DEPTH WITHIN 3/8"

-THE RECEPTACLE WITHIN 6 FT OF THE LAUNDRY SINK MUST BE

GFCI

-OPEN CAN LIGHTS AND PENDANT LIGHT NOT ALLOWED IN

MASTER CLOSET

-THE HANDRAIL OF THE STAIR TO BASEMENT SHALL BE CONTINUOUS THE WHOLE FLIGHT (LANDING TO LANDING) OF

STAIR, INCLUDING THE WINDER TREADS

-INSTALL BREAKER LOCK FOR HOOD AND OVEN

-PROVIDE GFCI-PROTECTED RECEPTACLE FOR SPACE UNDER GARAGE. ALSO INSTALL RECEPTACLE FOR DOOR OPENER

-FULLY NAIL THE RECEPTACLE BOX TO STUD

-TIGHTEN THE SE CONNECTORS TO PANELS

-SECURE ALL WIRINGS WITHIN 12" OF PANELS
-EXTERIOR DOORS IN BASEMENT-SECURITY CODE REQUIRES
THAT THE SECURITY STRIKE PLATE WITH 4-3" SCREWS BE
INSTALLED. THE STRIKE PLATE MUST BE SCREWED INTO THE
JAMB STUDS WITH THE 3" SCREWS. ADD 2X FRAMING TO MEET
THIS REQUIREMENT
-LOCATE AND MAKE ACCESSIBLE THE SEWER CLEANOUT AND THE
UFER GROUNDING CONNECTION

Comments: