

CODES ADMINISTRATION

Inspection Summary

Permit #: PRRES20170595, Building Permit - Residential Address: 1341 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underslab Plumbing Khanh Nguyen Failed Tuesday, April 11, 2017

Inspection - Residential

Corrective Action Required

1 -VENT THE SHOWER TRAP

Comments: