

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20161240,
The Summit Church
Address: 3381 NW CHIPMAN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Erosion Sediment Control (ESC) Inspection Informational	Steve Robbins	Partial	Wednesday, April 26, 2017
1	The erosion control is still in place because the 70 percent vegetation is not established yet. Steve Robbins 04/14/2017 1:27 PM		
Informational			
2	The erosion control is still good. They will put some more seed down to try and fill in the bare spots. The erosion control is doing good. Steve Robbins 04/26/2017 3:40 PM		

Comments: