

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #:	PRCOM20170898
Address:	196 NW OLDHAM PKWY, Unit:A, LEES SUMMIT, MO 64081
Inspected On:	Thursday, April 27, 2017
Inspected By:	John Borns
Expiration Date:	5/4/2017 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspector:	Outcome:	Date:	
John Borns	Temporary C of O	Thursday, April 27, 2017	
Corrective Action Required:			
AFFIX ACCESSIBLE RESTROOM SIGN AT DOOR			
Corrective Action Required:			
ANSI 603.3 MOUNTING OF MIRRORS AT ACCESSIBLE RESTROOMS:			
Corrective Action Required:			
ELECT RECPTS REQUIRED AT SERVICE COUNTER			
Corrective Action Required:			
NEC 600.4 ELECTRIC SIGN MARKINGS: SIGNS AND OUTSIDE LIGHTING SYSTEMS SHALL BE SHOP-LABELED WITH LISTING, MANUFACTURER'S NAME, TRADEMARK, OR OTHER MEANS OF IDENTIFICATION; AND INPUT VOLTAGE AND CURRENT RATING.			
	FFIX ACCESSIBLE REST NSI 603.3 MOUNTING ET BOTTOM OF VIEW LECT RECPTS REQUIRI EC 600.4 ELECTRIC SIG GHTING SYSTEMS SH IANUFACTURER'S NA	John Borns Temporary C of O FFIX ACCESSIBLE RESTROOM SIGN AT DOOR NSI 603.3 MOUNTING OF MIRRORS AT ACCES ET BOTTOM OF VIEWING SURFACE <= 40" AF LECT RECPTS REQUIRED AT SERVICE COUNTE EC 600.4 ELECTRIC SIGN MARKINGS: SIGNS A GHTING SYSTEMS SHALL BE SHOP-LABELED V IANUFACTURER'S NAME, TRADEMARK, OR O	