

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFC20160499, Public Works Infrastructure Permit - Commercial  
Hangar T

Address: 2751 NE DOUGLAS ST, Unit:T, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

**Inspection Item:**

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
PW-Hydrant Inspection	Steve Robbins	Failed	Friday, April 28, 2017

**Informational**

- 1 The fire hydrant on this property which was already there is not at the correct height. I talked to the contractor and he did not want to make it right. I then talked to Kent and it was determined he had to fix it, I called him today and I left him a message telling him he had to fix it.Steve Robbins 12/02/2016 12:59 PM

**Informational**

- 2 I came by to check to see if anything has been done with the fire hydrant. Nothing has been done yet to correct the problem.Steve Robbins 04/28/2017 10:33 AM

**Comments:**