

Inspection Summary

Permit #: PRCOM20151897, Building Permit - Commercial
Address: 1201 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	John Borns	Partial	Tuesday, May 16, 2017

Partial Correction
1 Misc

OK TO COVER WHEN READY CORRIDOR ACT CEILING FRAMING & ABOVE-CEILING SYSTEMS AT:
4TH FLOOR;
3RD FLOOR;
2ND FLOOR: LAUN CHUTE 233
1ST FLOOR: 112; 121/123/124; 122; 142; 126; 127; **128**; 129; 131 - 134; 137; 139; 140; 154;

Partial Correction
2 Misc

OK TO COVER WHEN READY ACT CEILING FRAMING & ABOVE-CEILING SYSTEMS AT 1ST FLOOR SPACES: MEETING [113];

Comments: