



RESIDENTIAL ENGINEERING SERVICES, LLC
INSPECTIONS · CONSULTING · ENVIRONMENTAL


May 16, 2017

Summit Custom Homes
120 SE 30th St.
Lee's Summit, MO 64082

Re: Deck connection to cantilever on Lot#95 Millcreek

This letter is to address failed framing inspection due to deck connection to cantilever at Lot #95 in Millcreek subdivision.

- RES has verified that the deck connection to the one foot cantilever is structurally sound as built, per the original engineered permit plans shown in the image below.



Sincerely,

Bradley Huxol, PE

