PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20163205, Building Permit - Residential Address: 4832 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Thursday, May 18, 2017

Residential

Corrective Action Required

1 Misc FRAMING:

-GARAGE PORTAL BRACE WALLS: SEAM IN SHEATHING SHALL BE WITHIN 24" OF THE WALL MID-HEIGHT; YOU HAVE A SEAM THAT IS JUST BELOW THE HEADER; SEAM SHALL BE BLOCKED AND NAILED PER CODE; STRAP THE INNER SIDE OF THE PORTAL PER DETAIL. SEE PLAN

**THE ROOFER CUT THE SHEATHING TO INSERT THE FLASHING. THIS REALLY COMPROMISE THE SHEARING CAPACITY OF THE BRACE WALL. YOU CAN HAVE THE ENGINEER ADDRESS FIX FOR THIS

***OK TO ROCK, EXCEPT AT THE GARAGE PORTAL WALLS. LEAVE

THESE AREAS OPEN

Comments: