

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20162991, Building Permit - Residential

Address: 2143 SW TIMBERTRACE LN, LEES SUMMIT, MO 640822145 SW TIMBERTRACE LN, LEES SUMMIT, MO 640822147 SW TIMBERTRACE LN, LEES SUMMIT, MO 640822141 SW TIMBERTRACE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Sidewalk Inspection	John DiMauro	Failed	Tuesday, May 30, 2017

Informational

1 John DiMauro 05/26/2017 2:12 PM
Forms are up and rock is compacted.

Corrective Action Required

2 John DiMauro 05/30/2017 3:46 PM
The east sidewalk's cross slope is greater than 2.0% The two center panels of this sidewalk need to be reinstalled.

Driveway Inspection	John DiMauro	Passed	Tuesday, May 30, 2017
---------------------	--------------	--------	-----------------------

Informational

1 John DiMauro 05/30/2017 1:47 PM
The cross slope of the driveway approach is less than 2.0%

Comments: