

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRCOM20160277, Building Permit - Commercial
Address: 1101 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	John Borns	Partial	Thursday, June 08, 2017

Partial Correction
1 Misc

OK TO COVER WHEN READY GWB CEILING /SOFFIT /LIGHT COVE FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING 1ST FLOOR SPACES: VESTIBULE @ MEN'S & WOMEN'S RESTROOMS 102 / 103; SOFFITS/FACIAS @ C104 LAB, 1-101, 1-117, 1-118; LIGHT COVE @ 1-151; HARD LID SOFFIT FIRST FLOOR AREA C A156; RR'S 102 & 103; A202; C202; C250; 206; 259; TENSION STUDS AT LIGHT SLOT CEILING AT N.2/9.3; BULKHEAD AT B152 E&S; HARD LID SOFFIT TENSION STUDS @ 4-150/151 & 152; BULKHEADS @ 4-101, 102, 103; SOFFIT AT CORRIDOR B155 EAST SIDE; TENSION STUDS SUPPORTING SOFFITS AT B151, B152; ROLLER SHADE POCKETS AT "C" A252 AND AT "A" A201; SOFFIT @ 3-250; SOFFIT + EYEBROW @ 205 INTNL STUDIES; [1-102 THRU 1-114; 1-117; 4-150 THRU 4-152; BULKHEADS AT 100A,100B, 2-150, 2-151; LIGHT COVE AT 4-156 & 4-157; SHADE POCKETS AT 2-101, 2-204, 2-205, 4-250 THRU 4-253; SHADE POCKETS AT B206; OUTER BAND OF FRAMING AROUND CLOUD CEILINGS AT B150 & B151; THREE CLOUD CEILINGS AT B150 & B151; TENSION STUDS SUPPORTING SOFFITS AT B250, B251, B252, TWO AT B207; BULKHEAD TENSION STUDS E-W ACROSS FULL LENGTH OF B250, B251, B252; MAIN COMMONS SOUTH 100A; **THREE SUSPENDED SOFFITS COMPLETE AT B250, B251, B252;**

Partial Correction
2 Misc

OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES:

A153C; A153D; A161; A163; [101C; 118; 119;
A250-252; [201 & CORR; 202-205; 207A; 209; 210; 212-216;

220-222; 278;

RESTROOMS 102 & 103

C101; C102; C102A; C103; C103A; C104; C105; C106; C150; C151;
C152; C154; C155; C155A; C155B; C156A; C157B; C159; [151A;
151B; STAIR 156;
C202; 203; 204A; 204B; 205; 205B-222; 224; 225; 250A; 252;-257;
260-270; 272-274; 277;

**Rated Assembly
Inspection**

John Borns

Partial

Thursday, June 08, 2017

Partial Correction

1 Misc

RATED DOOR HEAD ASSEMBLIES PER DETAILS 11/A7.03 &
12/A7.03:

OPENING 2-100.1: FRAMING & LINER BOARD @ INSIDE(W) FACE;
1ST LAYER 5/8" TYPE X GWB; 2ND LAYER 5/8" TYPE X GWB;

OPENING 4-100.1: FRAMING & LINER BOARD @ INSIDE(W) FACE;
1ST LAYER 5/8" TYPE X GWB AT WALLS/BULKHEAD; 2ND LAYER
5/8" TYPE X GWB AT WALLS/BULKHEAD; FRAMING & SHAFT
LINER BOARD AT CEILING; 1ST LAYER 5/8" TYPE X GWB AT
CEILING;
2ND LAYER 5/8" TYPE X GWB AT CEILING;

OPENING 2-200: FRAMING & LINER BOARD @ INSIDE(W) FACE;
1ST LAYER 5/8" TYPE X GWB; 2ND LAYER 5/8" TYPE X GWB;

OPENING 2-204: WALL FRAMING & LINER BOARD @ INSIDE(W)
FACE; WALL 1ST LAYER 5/8" TYPE X GWB; WALL 2ND LAYER 5/8"
TYPE X GWB; LID FRAMING & LINER BOARD OK TO COVER AFTER
FIRE-STOPPING IS COMPLETED; 1ST & 2ND LAYERS 5/8" TYPE X
GWB;

FRAMING & LINER BOARD @ N WALL OF B208;

**OPENING 2-207.1: FRAMING & SHAFT LINER BOARD; 1ST LAYER
5/8" TYPE X AT WALLS, BULKHEAD & SOFFIT;**

Comments: