
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20171247, Public Works Infrastructure Permit - Commercial
Saint Luke's - OR Expansion #2
Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Site Visit	John DiMauro	Partial	Friday, June 09, 2017

Informational

1 John DiMauro 06/07/2017 4:01 PM
No utility work.

Informational

2 John DiMauro 06/05/2017 2:33 PM
No utility or parking lot construction today.

Informational

3 John DiMauro 05/18/2017 2:14 PM
No utility or parking lot construction work at this time.

Informational

4 John DiMauro 05/08/2017 10:02 AM
Crews are on site working.

Informational

5 John DiMauro 05/09/2017 10:34 AM
Crews are on site today working on the storm sewer relocation.

Informational

6 John DiMauro 05/10/2017 3:40 PM
Crews on site today working on the storm and sanitary sewer lines.

Informational

7 John DiMauro 05/11/2017 11:25 AM
Crews on site working on the utility plans.

Informational

8 John DiMauro 05/12/2017 3:27 PM
Crews on site working today.

Informational

9 John DiMauro 05/15/2017 3:10 PM
Crews on site.

Informational

10 John DiMauro 05/22/2017 3:01 PM
No utility or parking lot construction work at this time.

Informational

11 John DiMauro 05/24/2017 3:23 PM
No utility or parking lot construction work at this time.

Informational

12 John DiMauro 05/31/2017 8:12 AM
No utility or parking lot construction work at this time.

Informational

13 John DiMauro 06/09/2017 3:36 PM
No utility work.

PW-Erosion Sediment Control John DiMauro
(ESC) Inspection

Partial

Friday, June
09, 2017

Informational

1 John DiMauro 06/05/2017 2:35 PM
Erosion control devices are intact.

Informational

2 John DiMauro 05/08/2017 9:56 AM
Project stage 1 erosion control devices are installed per the plans and intact.

Informational

3 John DiMauro 05/11/2017 11:28 AM
The erosion control devices are intact.

Informational

4 John DiMauro 05/15/2017 3:21 PM
The erosion control devices are intact.

Informational

5 John DiMauro 05/22/2017 3:03 PM
The erosion control devices are intact.

Informational

6 John DiMauro 05/24/2017 3:24 PM
The erosion control devices are intact.

Informational

7 John DiMauro 05/31/2017 8:13 AM
The erosion control devices are intact.

Informational

8 John DiMauro 06/09/2017 3:35 PM
Erosion control devices are intact.

Comments:
