PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161179, Building Permit - Commercial Address: 1820 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Failed Wednesday, June 14, 2017

Codes Commercial

Corrective Action Required

2 Misc VERIFY AND LABEL CIRCUIT POSITION NUMBERS AT UNIT

SUB-PANELS

Corrective Action Required

3 Misc PVC PIPE PENETRATIONS OF RATED CEILING ASSEMBLIES TO BE

FIRE-STOPPED PER APPROVED DRAWINGS

Corrective Action Required

4 Misc RESOLVE ISSUES PRESENTED BY:

FIRE DEPARTMENT

WATER UTILITIES DEPARTMENT

PLANNING DIVISION PUBLIC WORKS

Corrective Action Required

1 Misc BUILDING EXTERIOR:

- HEIGHT OF THRESHOLDS AT PATIO DOORS

- SEAL ALL OPENINGS IN EXTERIOR WALL

- SEAL AROUND DISCONNECT ENCLOSURES, ETC

- OPEN J.B. + MISSING FACE PLATE @ LINK

- COMPLETE INSTALLATION OF DOWNSPOUTS

- EXHAUST HOOD MISSING AT NORTH WALL 2ND LVL

- INSTALL GAS PRESURE REGULATOR

- PAINT EXTERIOR EXPOSED FERROUS GAS PIPING

- OPEN 4" PVC PIPE RISER NORTH OF BUILDING

- INSTALL PARKING LOT LIGHT POLE

- COMPLETE FINISH SITEWORK

Occupancy Inspection - Michael

Not Ready

Wednesday, June 14, 2017

Fire Weissenbach

Occupancy Inspection - Hector Soto Jr. Issues below Wednesday, June 14, 2017 Planning

Corrective Action Required

1 LANDSCAPING. Landscaping shall be completed per the

approved plan.

Corrective Action Required

PARKING LOT LIGHTING. Parking lot light poles and fixtures shall

be installed per the approved plan.

Corrective Action Required

3 PARKING LOT. The previously existing parking lot at the far

southwest corner of the site shall be re-striped when it is no

longer used as a staging area.

Comments: