

**PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201**

## Inspection Summary

---

Permit #:PRCOM20160277, Building Permit - Commercial  
Address: 1101 NW INNOVATION PKWY, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Miscellaneous Inspection</b>	John Borns	Partial	Tuesday, June 27, 2017

Partial Correction  
1 Misc

FOLLOWING SPACES ARE NOT APPROVED FOR OCCUPANCY BUT  
MAY BE USED FOR TEMPORARY STORAGE OF FF&E OR HAVE  
FURNITURE PLACED IN PERMANENT POSITION:

A101B; 102 - 116; A165;  
A203; A204; A205; A207;

C101; C106; C150; C152;  
C222; C251 - C254; C256; C257; C260 - C270; C272 - C275; C277;  
C278;

104; 105; 106; 205A; 205B;

1-101A; 101C; 1-159A; 1-164;  
1-207A; 1-209; 1-210; 1-212; 1-213; 1-216; 1-217; 1-220; 1-221;  
[1-159;

3-102A; 3-103A; 3-105; 3-152; 3-152A; 3-155; 3-155A; 3-157B;  
3-203; 3-204A; 3-204B; 3-205; 3-210; 3-215; 3-216; 3-218; 3-220;  
3-221; 3-258; 3-259; [3-157; 3-158;

<b>Above Ceiling Inspection</b>	John Borns	Partial	Tuesday, June 27, 2017
-------------------------------------	------------	---------	------------------------

Partial Correction  
1 Misc

OK TO COVER WHEN READY GWB CEILING /SOFFIT /LIGHT COVE

FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING 1ST FLOOR SPACES: VESTIBULE @ MEN'S & WOMEN'S RESTROOMS 102 / 103; SOFFITS/FACIAS @ C104 LAB, 1-101, 1-117, 1-118; LIGHT COVE @ 1-151; HARD LID SOFFIT FIRST FLOOR AREA C A156; RR'S 102 & 103; A202; C202; C250; 206; 259; TENSION STUDS AT LIGHT SLOT CEILING AT N.2/9.3; BULKHEAD AT B152 E&S; HARD LID SOFFIT TENSION STUDS @ 4-150/151 & 152; BULKHEADS @ 4-101, 102, 103; SOFFIT AT CORRIDOR B155 EAST SIDE; TENSION STUDS SUPPORTING SOFFITS AT B151, B152; ROLLER SHADE POCKETS AT "C" A252 AND AT "A" A201; SOFFIT @ 3-250; SOFFIT + EYEBROW @ 205 INTNL STUDIES; [1-102 THRU 1-114; 1-117; 4-150 THRU 4-152; BULKHEADS AT 100A,100B, 2-150, 2-151; LIGHT COVE AT 4-156 & 4-157; SHADE POCKETS AT 2-101, 2-204, 2-205, 4-250 THRU 4-253; SHADE POCKETS AT B206; OUTER BAND OF FRAMING AROUND CLOUD CEILINGS AT B150 & B151; THREE CLOUD CEILINGS AT B150 & B151; TENSION STUDS SUPPORTING SOFFITS AT B250, B251, B252, TWO AT B207; BULKHEAD TENSION STUDS E-W ACROSS FULL LENGTH OF B250, B251, B252; MAIN COMMONS SOUTH 100A; THREE SUSPENDED SOFFITS COMPLETE AT B250, B251, B252; TWO SUSPENDED SOFFITS AT 2-207; CEILING AT MAIN COMMONS N END NEAR ENTRANCE; 2-101; 4-250; 4-251; 4-252; 4-253;

Partial Correction  
2 Misc

OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES:

A101C; A118; A119; A153C; A153D; A161; A163;

A201 & CORR; A202-205; A207A; A209; A210; A212-216; A220-222; A250-252; A278;

RESTROOMS 102 & 103

C101; C102; C102A; C103; C103A; C104; C105; C106; C150; C151; 151A; 151B; C152; C154; C155; C155A; C155B; STAIR 156; C156A; C157B; C159;

C202; 203; 204A; 204B; 205; 205B-222; C224; C225; C250A; C252;-257; C260-270; C272-274; C277;

**4-264;**

**Comments:**