PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161756, Building Permit - Commercial Address: 795 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Friday, July 14, 2017
Partial Correction 1 Misc	0 N 1 2 P W & 8 5 1 1 2	RATED ASSEMBLY AT STAIRWELLS: OK TO COVER 5/8" TYPE X MOLD TOUGH GWB AT NORTH STAIRWELL WALLS: 2ND LAYER AT 1ST LEVEL WELL FACE + 1ST LAYER PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 2ND LEVEL WELL FACE; 2ND LAYER AT 2ND LEVEL WELL FACE + PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 3RD LEVEL WELL FACE; PRE-ROCK AT JOIST SPACE AT BACKSIDE AT 1ST, 2ND & 3RD FLOORS; 1ST LAYER AT 4TH FLOOR; SOUTH STAIRWELL WALLS: 2ND LAYER AT 1ST LEVEL WELL FACE + 1ST LAYER PRE-ROCK AT JOIST SPACE AT BACKSIDE; 1ST LAYER AT 2ND LEVEL WELL FACE; 2ND LAYER AT 2ND LEVEL WELL FACE +	
	V		BACKSIDE; 1ST LAYER AT 3RD LEVEL DIST SPACE AT BACKSIDE; 1ST LAYER
Partial Correction			
2 Misc	S		RATED ASSEMBLY AT ELEVATOR RIMETER PRE-ROCK AT JOIST SPACE RS:
Partial Correction		, ,	,
3 Misc		K TO COVER AT RATED COR ST FLOOR: 1ST LAYER 5/8" T	
Corrective Action Require	ed		
4 Misc	V	ERTICAL FIRE-BLOCKING AT LOSE GAPS AT MID-HEIGHT	

Comments: