PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161178, Building Permit - Commercial Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Gas Piping Inspection - John Borns Partial Thursday, July 27, 2017

Commercial

Partial Correction

1 Misc GAS FEEDER PIPE FROM DISTRIBUTION LINE AT OBRIEN RD TO S

WALL OF BLDG HELD STEADY AT 95 PSI FOR >20 MINUTES. PIPE

DEPTH IN TRENCH OK TO COVER WHEN READY.

Hood/Duct Inspection John Borns Failed Thursday, July 27, 2017

Partial Correction

1 Misc LIGHT TEST OF GREASE DUCT SHOP WELDS OF SEAMS: ONE HOLE

FOUND -- TO BE SPOT-WELDED; THEN OK TO HANG. REQUEST

LIGHT TEST OF FIELD WELDS WHEN READY.

LIGHT TEST OF JOINT FIELD WELDS: NOT APPROVED.

Above Ceiling John Borns Partial Thursday, July 27, 2017

Inspection

Partial Correction

1 Misc OK TO COVER WHEN READY GWB CEILING / SOFFIT FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: C102; 104; 106; 107; C104 - C108; C115; C118; C119; C121 - C129; 123; C131 - C134; C137 - C138; C140; C142 - C144; C146 - C149; C154 - C159; FOUR CLOUD CEILINGS AT AEROBICS 157; C163; SOFFITS AT 113 INCLUDING EAST 12' (RD PENETRATION OF RATED WALL AT SOUTH YET TO BE RESOLVED); SOFFITS AT 118; SOFFITS AT 126

EXCEPT S 10'; CEILING @ 129;

Comments: