

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRRES20170201, Building Permit - Residential

Address: 2233 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822235 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822237 SW BURNINGWOOD LN, LEES SUMMIT, MO 640822231 SW BURNINGWOOD LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	John DiMauro	Partial	Thursday, July 27, 2017

Corrective Action Required

1 John DiMauro 07/27/2017 2:29 PM  
The driveway approach cross slope is less than 2.0% The curb for the driveway approach needs to be replaced.

PW-Sidewalk Inspection	John DiMauro	Passed	Thursday, July 27, 2017
------------------------	--------------	--------	----------------------------

Informational

1 John DiMauro 07/24/2017 3:18 PM  
Forms are up and rock is compacted.

Informational

2 John DiMauro 07/27/2017 2:32 PM  
Sidewalk cross slope is less than 2.0%

**Comments:**