PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20163237, Building Permit - Residential Address: 1340 NE BRANDYWINE RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - Dale Carter Failed Tuesday, August 01, 2017

Codes Residential

Corrective Action Required

1 Misc 1. Final grade, downspouts, splashblocks, sod, etc.

2. Seal exterior penetrations.

- 3. Secure guardrail post at northwest side of deck.
- 4. Deck stair needs graspable handrail.
- 5. Missing joist hangers and nails in existing joist hangers at deck.
- 6. Deck cannot be anchored to cantelever (unless specifically

designed for such).

- 7. Cedar deck post cannot be in contact with grade.
- 8. Secure elec. recept. yokes throughout.
- 9. Lock-out/Tag-out bracket needed in breaker panel for

over-range hood circuit.

10. Need 2nd lock on sliding doors at master bedroom and

downstairs.

11. Main-floor laundry receptacle needs to be GFI protected

(within 6' of sink).

Erosion Control Dale Carter Partial Tuesday, August 01, 2017

Corrective Action Required

1 Misc Clean street and establish temporary erosion control until sod is

installed.

Comments: