PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161761, Building Permit - Commercial Address: 805 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	John Borns	Partial	Friday, August 11, 2017	
Partial Correction 1 Misc		STAIRWELLS: SOUTH STAIRWELL: BASEMENT: 1ST & 2ND INCLUDING PRE-ROCK E FIRST FLOOR 1ST LAYER JOIST BAYS; 2ND LAYER SECOND FLOOR: 1ST LAY BACKSIDE JOIST BAYS; 2 LAYER AT WELL FACE;	ENTS OF RATED ASSEMBLIES AT LAYER 5/8" TYPE X MOLD-TOUGH GW BACKSIDE JOIST BAYS; @ WELL FACE + PRE-ROCK AT BACKSI PRE-ROCK AT BACKSIDE JOIST BAYS; YER @ WELL FACE + PRE-ROCK AT IND LAYER PRE-ROCK AT JOIST BAYS; [ER @ WELL FACE + PRE-ROCK AT	IDE
		JOIST BAYS; 2ND LAYER SECOND FLOOR: 1ST LA' BACKSIDE JOIST BAYS; 2 LAYER AT WELL FACE;	@ WELL FACE + PRE-ROCK AT BACKSI PRE-ROCK AT BACKSIDE JOIST BAYS; YER @ WELL FACE + PRE-ROCK AT ND LAYER PRE-ROCK AT JOIST BAYS; [ER @ WELL FACE + PRE-ROCK AT	

BACKSIDE JOIST BAYS;

Partial Correction 2 Misc

RATED ASSEMBLIES AT ELEVATOR SHAFT:

BASEMENT: 1ST & 2ND LAYERS PRE-ROCK AT BACKSIDE JOIST BAYS

FIRST FLOOR: 1ST & 2ND LAYERS PRE-ROCK AT BACKSIDE JOIST BAYS

SECOND FLOOR 1ST LAYER PRE-ROCK AT BACKSIDE JOIST BAYS; 2ND LAYER PRE-ROCK AT JOIST BAYS;

THIRD FLOOR: [1ST LAYER PRE-ROCK AT BACKSIDE JOIST BAYS;

Comments: